RECEIVED AUG 122014

State of Washington UTC Pipeline Safety Program



Mr. David D. Lykken Pipeline Safety director

Dear Mr. Lykken:

Staff from WUTC conducted 2 days inspection in our facility in June 3, 2014, and there was one concern that we have not complied with API inspector recommending that the Breakout Tank T-115 should have a moisture barrier caulking between the foundation and the tank shell.

Our intention now is to follow their recommendation. We started pressure washing and cleaning the concrete foundation. We ordered the sealant and will be arriving in a week for immediate application.

Dean Williams

General Manager